57.84 b)(2)	2020 REPORT OF ANNIJAL INSPECTION OF CCR LANDELL	
	OWNER OF CCR LANDFILL: Georgia Power Company	
	INSPECTION DATE: 11/20/2020	
	INSPECTING ENGINEER: Gary H. McWhorter, P.E. GA Reg. #PE012687	
(i)	ANY CHANGES IN GEOMETRY OF THE STRUCTURE SINCE THE	NO ⁽¹⁾
	PREVIOUS ANNUAL INSPECTION?	NO
	(IF YES, DESCRIBE):	
(ii)	APPROXIMATE VOLUME OF CCR CONTAINED IN THE UNIT AT THE	563,274 ⁽²
	TIME OF INSPECTION?	
(iii)	ANY APPEARANCE OF AN ACTUAL OR POTENTIAL STRUCTURAL	NO
	WEAKNESS OF THE CCR UNIT, IN ADDITION TO ANY EXISTING	
	CONDITIONS THAT ARE DISRUPTING OR HAVE THE POTENTIAL TO	
	DISRUPT THE OPERATION AND SAFETY OF THE CCR UNIT?	
	(IF YES, DESCRIBE):	
(iv)	ANY OTHER CHANGE(S) WHICH MAY HAVE AFFECTED THE STABILITY OR OPERATION OF THE CCR UNIT SINCE THE PREVIOUS ANNUAL INSPECTION?	NO
	(IF YES, DESCRIBE):	

⁽¹⁾ The geometry of the structure (permitted footprint and final grades) has not changed since the last inspection, with the exception of the additional placement or marketing of CCR.

(2) Approximate CCR volume (by survey dated Dec. 2020): Cell 1-434,718 cy; Cell 2-50,248 cy; Cell 3-78,308 cy.